



Core	% Rec.	Hardness	R.Q.D.
C1	100	R0-R2	0
C2	100	R0-R2	0
C3	100	Very Soft (R1)	
C4	100	Extremely Soft (R0)	